

Outer Beacon Port Columbus ILS

Herrick Archives Building S 13

A. IDENTIFICATION & LOCATION

1. Name

1.1 Never officially named by Board of Trustees action.


1.2 Alternate names noted:

Outer Marker

2. Location

2.1 Located at 2261 North Fyffe Road (arbitrarily assigned for indexing purposes). See map below

2.2 For greater detail, see Sheets 42 and 43 in the book of campus maps in the University Archives.



beacon of the instrument landing system for the north runway of Port Columbus. Land for this constructed is leased to the FAA under authority granted by the Board of Trustees on July 10, 1959. The building was constructed shortly after Board approval.

C. PHOTOGRAPHS

1. In Photoarchives:

X 7339

John H. Herrick

March 26, 1976